



Bight Release Hook, Command Unit -Frame Asset Summary

Type	View Data Sheet	View History	Equip. Asset no.	Equipment Description	Location
Command Unit			CU 1	TTS01A S/N 04	Oast Portland
Command Unit			CU 2	TTS01A S/N 082	Oast Portland
Command Unit			CU 8	TTS01A S/N 094	Oast Portland
Command Unit			CU 10	TTS01A S/N 232	Oast Portland
Command Unit			CU 12	TTS01A S/N 237	Wave Mercury
Command Unit			CU 14	TTS01A S/N 236	Oast Portland
Command Unit			CU 15	TTS01A S/N 280	Cable Innovator
Command Unit			CU 17	TTS01A S/N 38	Oast Portland
Command Unit			CU 19	TTS01A S/N 226	Pacific Guardian
Command Unit			CU 20	TTS01A S/N 271	Cable Retriever
Command Unit			CU 21	TTS01A S/N 243	Oast Portland
Command Unit			CU 22	TTS01A S/N 301	CS Sovereign
Command Unit			CU 23	TTS01A S/N 279	Wave Venture
Command Unit			CU 24	TTS01A S/N 233	Oast Portland
Command Unit			CU 25	TTS01A S/N 160	Oast Portland
Command Unit			CU 26	TTS01A S/N 234	Wave Sentinel
Note: TT301B Until serial no. 250 is un-assigned an in need of repair, it has no case, 24V lead or 4 pin hydrophone.					